

## Exmouth Town Council

### Waterfront Working Party – 26<sup>th</sup> October 2021

#### Inspection Sheet

Present:

Councillor Pauline Stott (PS), Exmouth Town Council (ETC)  
Councillor Eileen Beech (EB), Exmouth Town Council  
Councillor Tim Dumper (TD), Exmouth Town Council  
Councillor David Poor (DP), Exmouth Town Council  
Councillor Steve Gazzard (SG), Exmouth Town Council  
Councillor Joy Whipps (JW), Exmouth Town Council  
Chetna Jones (CJ), Exmouth Town Council  
Anna Jones (AJ), Exmouth Town Council  
Lisa Greenway (LG), Exmouth Town Council  
Peter Blyth (PB), East Devon District Council (EDDC)  
David Radford (DR), Exmouth Sea Scouts

Apologies for Absence:

Councillor Fred Caygill (FC), Exmouth Town Council

Item	Location	Issue	Resolution
Broken railing	Seawall	Broken railing on the beach (see Image 1)	<i>Where EDDC is mentioned, the Area Manager of Streetscene to action</i> PB stated EDDC are waiting for spare parts
Seawall	Various	Various cracks and breaks in the top of the seawall	EDDC to repair On-going
Fingerpost	Seafront (opposite Premier Inn)	Damaged fingerpost, missing one black sign (see Image 2)	PB to check for broken finger at Camperdown depot and ETC to arrange for repair
Windows	The Bath House	Signs on the windows	ETC to investigate potential advertising breach
Beach steps	From main path onto the beach	Only one metal handrail, not one either side like the others	Not completed, EDDC to sort parts
Showers	The Octagon	Showers do not work	EDDC aware and are reviewing
EDDC Flagpole	On beach near Sea Shore Ice Cream Creamery	Flagpole taken down and replaced by signs	RNLI confirmed red flag not required as signs have been added on the beach
Wall	Between the 1 <sup>st</sup> garden at Beach Gardens and the pedestrian/cycle path	Wall broken (see Image 3)	EDDC to repair
Signs	Beach Gardens	Blenny Bay signs	PB stated EDDC will change sign headers and consulting with community on changing name of Blenny Bay, final decision to be made by EDDC
Two Shelters	Beach Gardens	Graffiti/stickers, rotten wood on base and windowsills, paint peeling and some	PB to follow up with property services

		inside roof panels warping	
Flagpole	Pavilion Carpark	Flag to be flown	CJ/PB to order and fit, contact Hampshire Flags about flagpoles
Carpark signposts	Pavilion Carpark	Sign removed and only posts remaining	PB has reported to carparks team
Carpark sign	Pavilion Carpark	Carpark sign looking tatty	PB to report to carparks team
Railings	On beach at Abode	Loose railing	Streetscene to repair
Broken bollard piece	By bench on seafront	Broken bollard piece next to bench (see Image 4)	Needs removing by Streetscene
Metal railings	Outside Beach Wheelchair Hut on Queen's Drive	Metal railings need painting	Railings to be painted by ETC
Exposed groynes	On beach under Lifeboat Station ramp	Sand loss has exposed broken wooden groynes	Lifeboat contractors to remove groynes whilst they carry out remedial work
Wooden board	On beach near Lifeboat Station	Broken wooden board behind exposed pipe by the Lifeboat Station (see Image 5)	PB stated EDDC will remove the wooden board but nothing can be done about the concrete
Loose handrail	Steps by RNLI	Loose handrail at the steps by the Lifeboat Station	Reported to PB